

MODEL NUMBER	98C	122C	146C
Number of Axes	3/4	3/4	3/4
Table Size	96" X 60"	120" X 60"	144" X 60"
Z Clearance	14"	14"	14"
X-Axis Travel	71"	71"	71"
Y-Axis Travel	124"	156"	164"
Z-Axis Travel	11"	11"	11"
Approx. Footprint	11' X 14'	11' X 17'	11' X 17'
Machining Speed	3600 ipm	3600 ipm	3600 ipm
X & Y Rapid Traverse	4800 ipm	4800 ipm	4800 ipm
Standard Spindle	18HP 24,000 rpm	18HP 24,000 rpm	18HP 24,000 rpm
Tool Shank	HSK 63F	HSK 63F	3/4
Standard Tool Capacity	12	12	12
Standard Vacuum Zones	2	2	4